



Wood Lathe

!! OFF LIMITS WITHOUT SPECIFIC PERMISSION, TRAINING, AND SUPERVISION



1. **Configuration: two spindles equipped with a parallel tool rest**
2. **Action:**
 - a. The lathe is used to “turn” or cut rectangular pieces into cylindrical forms
 - b. The wood is mounted between the spindles and spun, while turning chisels are used to cut the cylindrical profiles.
3. **Adjustments:**
 - a. Spindles accommodate various lengths
 - b. Variable speed
 - c. Adjustable tool rest
 - d. Variety of chisels
4. **Safety: Do not use without specific permission, training, and direct supervision.**